

**IEther-00 (iether)
Gigabit Ethernet Driver
for HP-UX 11i v2 and 11i v3
of March 2008
Release Notes**

IEther-00 Software Version B.11.23.0308 and B.11.31.0308

Printed in U.S.A.



i n v e n t

Legal Notices

The information in this document is subject to change without notice.

Hewlett-Packard makes no warranty of any kind with regard to this manual, including, but not limited to, the implied warranties of merchantability and fitness for a particular purpose. Hewlett-Packard shall not be held liable for errors contained herein or direct, indirect, special, incidental or consequential damages in connection with the furnishing, performance, or use of this material.

Warranty

A copy of the specific warranty terms applicable to your Hewlett-Packard product and replacement parts can be obtained from your local Sales and Service Office.

Restricted Rights Legend

Use, duplication or disclosure by the U.S. Government is subject to restrictions as set forth in subparagraph (c) (1) (ii) of the Rights in Technical Data and Computer Software clause at DFARS 252.227-7013 for DOD agencies, and subparagraphs (c) (1) and (c) (2) of the Commercial Computer Software Restricted Rights clause at FAR 52.227-19 for other agencies.

HEWLETT-PACKARD DEVELOPMENT COMPANY L.P.
20555 S.H. 249
Houston, Texas 77070

Use of this document and any supporting software media supplied for this pack is restricted to this product only. Additional copies of the programs may be made for security and back-up purposes only. Resale of the programs, in their present form or with alterations, is expressly prohibited.

Copyright Notice

Copyright © 1997-2008 Hewlett-Packard Development Company L.P.
Reproduction, adaptation, or translation of this document without prior written permission is prohibited, except as allowed under the copyright laws.

IEther-00 (iether) Gigabit Ethernet Driver for HP-UX 11i v2 and 11i v3 of March 2008 Release Notes

What's in this Version

The following information describes the updates made to the HP-UX-based Gigabit Ethernet driver called **iether**. The **IEther-00** software bundle, which is loaded into the OE, contains the **iether** driver.

The March 2008 version of the HP-UX 11i v3 and HP-UX 11i v2 **IEther-00** driver has been modified to include the following *fixes*:

- QXCR1000750213 (HP-UX 11i v3) and QXCR1000741988 (HP-UX 11i v2)

The `lanadmin` command was changed to correctly display vital product data information. Changes were made to `iether_preinit` and `lanadmin -x vpdprod description`.

- QXCR1000593020 (applies to HP-UX 11i v3 of September 2007 and HP-UX 11i v2 of June 2007 or later)
Severity - serious

Fixed the **iether** driver to prevent FCS errors on PCIe card when speed was set to 100hd manual over copper cabling. Condition was observed during back-to-back setup between PCIe card and PCI-X, both are operating in 100HD manual mode over copper cabling. The FCS errors were seen on the PCIe side.

What's in this Version